#### REHABILITATION/RESTORATION/MAINTENANCE PLAN

Use this template to create a detailed work plan to be completed in the first 10 years of the contract. Recall that all work must be consistent with the Secretary of the Interior's Standards for Rehabilitation (see Application Guide Appendices), and properties which have already been fully rehabilitated or restored, and do not need additional work, are not eligible. Work that is visible from the public right-of-way, corrects any critical systems or structural deficiencies, and preserves historic features of the property should be given first priority. Duplicate this form as needed or provide additional sheets to include all work plan items. Remember that all exterior work on historic properties requires prior City approval through a Certificate of Appropriateness, and that any unpermitted work could be subject to fines, penalties, or might have to be modified, removed or redone at owner expense.

3735 Cerritos Ave, Long Beach, CA 90807

Property Name and Address: Detailed description of work: Item No.: Original Door is in good shape. There is a visible gap between Building Feature: Battened Arched Front Entrance North Side interior floor and bottom of door. To remedy draft and visible error, add floor transition piece to eliminate gap. Completion Year: 20 Specify/list: Plan to Use Long Beach Vendors For Materials/Labor: ✓ Yes (If Yes, specify/list) Detailed description of work: Item No.: Exposed Romex and Loose Covers need to Addressed in Back of Building Feature: Electrical is out of date and need Garage. Long Beach Licensed Electrician to review loose romex upgrading and wires for safety issues and remove multiple electrical wires not in use. Completion Year: 20 \_\_\_\_\_ Plan to Use Long Beach Vendors For Materials/Labor: Specify/list: Yes (If Yes, specify/list) 

3735 Cerritos Ave, Long Beach, CA 90803

#3 Item No.:  Building Feature: Visible Plumbing Issues, Water Heater enclosures in Rear of House are broken, Rusted Pipes are visisble.  19 Completion Year: 20	Detailed description of work:  Water Heater Enclosure is Broken. Sides and Legs coming Apart.  Some Rust noted in Piping. Have Long Beach Licensed Plumber review stability of prior installations and rebuild Water Heater enclosure and address rust issues.
Plan to Use Long Beach Vendors For Materials/Labor:  Yes (If Yes, specify/list)   No	Specify/list: Long Beach Licensed Plumber: Primo Plumbing
#4	Detailed description of work:
Building Feature: Street View Tree (South Side)	Old Tree Roots Effecting Foundation. Remove Tree and Roots Replace with Non-Evasive Shrubs compliment to the house and the surrounding community to protect further damage to foundation.
19 Completion Year: 20	
Plan to Use Long Beach Vendors For Materials/Labor:  Yes (If Yes, specify/list)	Specify/list:
#5	Detailed description of work:
Building Feature: Spearhead Awnings over Front Porch (North Side)	Demolish and replace existing aluminum awning; current awning is an eye-sour and does not provide for the beauty of the Spearhead Awning design for the house. Will replace the aluminum awning with a Spearhead Awning using Sunbrella and wrought iron posts.
Completion Year: 20	
Plan to Use Long Beach Vendors For Materials/Labor:  Yes (If Yes, specify/list)   No	Specify/list: Preliminary Proposal from Long Beach Contractor

3735 Cerritos Ave, Long Beach, CA 90807

#6	Detailed description of work:
Item No.:  Building Feature: North\East\West\South Landscaping	Neglect Landscaping result in dead shrubs and broken sprinklers. Fix sprinklers, replace some shrubs and reinvigorate Current plants and shrubs. Add landscaping in dirt areas.
19 Completion Year: 20	
Plan to Use Long Beach Vendors For Materials/Labor: ☑ Yes (If Yes, specify/list) □ No	Specify/list:
#7	Detailed description of work:
Item No.:	Foundation is not bolted and has exposed concrete with a brick
Building Feature: Foundation Not Bolted or Retrofitted	foundation. The Foundation will be earthquake reinforced. (See Foundation Report)
2020	
Completion Year: 20	
Plan to Use Long Beach Vendors For Materials/Labor:  Yes (If Yes, specify/list)   No	Specify/list: Foundation Doctor
#8	Detailed description of work:
Building Feature: Portico Style Wrought Iron Railings and Red Brick Balusters (Along Cerritos Ave)	Original Front Red Brick Balusters and Wrought Iron Fence badly weathered worn, and rusted but are salvageable. Weld wrought iron fence back onto brick balusters. Scrape and paint wrought iron. Repair brick balusters if damage by iron repairs. Retain original
2021 Completion Year: 20	brick
Plan to Use Long Beach Vendors For Materials/Labor:	Specify/list: Preliminary Proposal from Long Beach Contractor

3735 Cerritos Ave, Long Beach, CA 90807

Property Name and Address:

#9 Item No.:	Detailed description of work:
Windows Main Elevation: 3-Multi-light  Building Feature: Paired Casement Arched Opening; 5-  Multi-Light Paired Casement; 4-Single  Double-Hung	Severe paint peeling, termite and weather damage. 3 single double-hung windows are missing wood trim. Scrape, repair dry rot wood, and pain all windows. Missing wood trim will be created and added to match existing windows.
21 Completion Year: 20	
Plan to Use Long Beach Vendors For Materials/Labor:	Specify/list: Preliminary Proposal from Long Beach Contractor
#10 Item No.:	Detailed description of work:
Building Feature: Fixed Center, Side Casements with matching Screens on Street Front	Original Door Height Windows are badly damaged from weather, termites and peeling paint for years. The Windows are salvageable. Scrape the wood, fixed any termite damage, repair wood pieces to match original and paint the window trims.
Completion Year: 20	
Plan to Use Long Beach Vendors For Materials/Labor:	Specify/list: Preliminary Proposal from Long Beach Contractor

<u>NOTE</u>: Please ensure that the current condition of all building features proposed for rehabilitation/restoration/maintenance as part of this work plan are clearly photographed or otherwise documented and labelled as required, and submitted with the Mills Act Application (see Application Guide page 10).

This form is available in alternative format by request at 562.570.3807. For an electronic version, visit our website at www.lbds.info.

#### REHABILITATION/RESTORATION/MAINTENANCE PLAN

Use this template to create a detailed work plan to be completed in the first 10 years of the contract. Recall that all work must be consistent with the Secretary of the Interior's Standards for Rehabilitation (see Application Guide Appendices), and properties which have already been fully rehabilitated or restored, and do not need additional work, are not eligible. Work that is visible from the public right-of-way, corrects any critical systems or structural deficiencies, and preserves historic features of the property should be given first priority. Duplicate this form as needed or provide additional sheets to include all work plan items. Remember that all exterior work on historic properties requires prior City approval through a Certificate of Appropriateness, and that any unpermitted work could be subject to fines, penalties, or might have to be modified, removed or redone at owner expense.

Property Name and Address: \_\_\_\_ Detailed description of work: Item No.: The rear (west) exterior wall of the house has decorative clay tile motif. The clay tile motif has stains and weather damage. The Tiles Building Feature: Decorative Clay Tile (Rear Exterior Wall) will be cleaned, repaired and restored. 21 Completion Year: 20 \_\_\_ Specify/list: Plan to Use Long Beach Vendors For Materials/Labor: Detailed description of work: 12 Item No.: Current Chimney is non-functional. Investigate problem, fix chimney Building Feature: Stucco Chimney (South Side) and make operative. Patch Stucco and Fix Red Brick circling chimney. Stucco to match the rest of the house. Completion Year: 20 Specify/list: Plan to Use Long Beach Vendors For Materials/Labor: Yes (If Yes, specify/list) 

3735 Cerritos Ave, Long Beach, CA 90803

#13	Detailed description of work:
Building Feature: Asymmetrical Rear Porch	Wood is Exposed. Clean and Stain to Stop Further Deterioration. Wood cover to Piping is Broken. Scrape, repair, paint, and reinstall wood panel.
21 Completion Year: 20	
Plan to Use Long Beach Vendors For Materials/Labor:	Specify/list:
#14	Detailed description of work:
Building Feature: Craftsman Wood Sidings on Garage Façade with Decorative Grille (Street View)	The Wood Sidings and the Decorative Grille are salvageable. The cluster of wood sidings and the grille are in serious need of repair due to weather, termite and peeling paint damage. Will scrape, sand and paint to show its beauty.
Completion Year: 20	
Plan to Use Long Beach Vendors For Materials/Labor:	Specify/list: Preliminary Proposal from Long Beach Contractor
item #15	Detailed description of work:
Building Feature: Stucco Cladding House Exterior	Visible signs of paint peeling and cracks in exterior walls and trim result of neglect and weather. House and Trim will be repaired, patched, and termite damage repaired before paint. Paint will be traditional color scheme.
Completion Year: 20	
Plan to Use Long Beach Vendors For Materials/Labor:	Specify/list: Preliminary Proposal from Long Beach Contractor

3735 Cerritos Ave, Long Beach, CA 90807

#16	Detailed description of work:	
Item No.:		
Building Feature: Foundation Concrete & Grading around House	Grading needs to be remedy to have water flow away from the house, as water damage is visible throughout the concrete driver and walkways. Driveway has severe water damage and cracks from the grading and will need to be demolish and re-poured.	
23 Completion Year: 20		
Plan to Use Long Beach Vendors For Materials/Labor:  Yes (If Yes, specify/list)	Specify/list: Preliminary Proposal from Long Beach Contractor	
#17	Detailed description of work:	
Building Feature: Carriage Garage Door (Street View)	Garage Door is the Original Carriage Barn Doors and Track. The Doors are not salvageable due to neglect, weather, termites and lack of paint for years. Demolish existing doors, replicate the doors and rebuild new tracks. Salvage Fixtures if possible.	
Completion Year: 20		
Plan to Use Long Beach Vendors For Materials/Labor:  Yes (If Yes, specify/list)	Specify/list: Preliminary Proposal from Long Beach Contractor	
#18	Detailed description of work:	
Building Feature: Carriage Driveway Gate Posts and Lighting (Street View):	Stucco Driveway Posts with Lamps are in need of repair due to weather, neglect and foundation movement. Both Posts have detached from the house. Demolish, Rebuild and Re-attach Stucco Posts. Lamps are rusted and not in working order. Restore or Re-	
25 Completion Year: 20	install the new Lamps and Correct Electrical for Lighting.	
Plan to Use Long Beach Vendors For Materials/Labor:	Specify/list: Preliminary Proposal from Long Beach Contractor	


3735 Cerritos Ave, Long Beach, CA 90807

Duning and Children and all Andrews are	3/33	Cernios Ave,	Long	peach,
Property Name and Address:				

#19	Detailed description of work:
Item No.:Building Feature: Carriage Driveway Gate (Street View	The Driveway Entrance appears to have had a Gate attached to the posts. Will recreate and install a Battened Arch Carriage Entrance Gate into the driveway area to match the Front Half-Round Arch Entrance Door to the house.
25 Completion Year: 20	
Plan to Use Long Beach Vendors For Materials/Labor:   ✓ Yes (If Yes, specify/list) □ No	Specify/list: Preliminary Proposal from Long Beach Contractor
#20 Item No.:	Detailed description of work:
Building Feature: Battened Arch Side Gate (South Side)	The current gate is broken and not of standard. Will demolish existing gate and re-install a Battened Arch Side Gate to match the current Battened Arch Front Entrance Door.
Completion Year: 20	
Plan to Use Long Beach Vendors For Materials/Labor:	Specify/list: Preliminary Proposal from Long Beach Contractor

<u>NOTE</u>: Please ensure that the current condition of all building features proposed for rehabilitation/restoration/maintenance as part of this work plan are clearly photographed or otherwise documented and labelled as required, and submitted with the Mills Act Application (see Application Guide page 10).

This form is available in alternative format by request at 562.570.3807. For an electronic version, visit our website at www.lbds.info.



127.50' South Property Line

PROJECT ADDRESS:

8:0"

15-6"

Larry and Clare Holmes 3735 Cerritos Avenue Long Beach, CA 90807 1.562.619.2587



SITE & I-O'

**DRAFTING SERVICES** 

SCALE: NONE

DO NOT SCALE DRAWING

All drawings and written material appearing herein constitute original and unpublished work of MSR Design and may not be duplicated, used or disclosed without written consent from MSR Design

2-28-2018

SITE

JOB NUMBER


MSR-10277

REVISION

SHEET NUMBER

A-1.2





Front View of Garage