# Arlington Avenue Flooding


February 7, 2009

### Existing Drain System





River Avenue Storm Drain City of Long Beach



### Existing Drain System Inlets





River Avenue Storm Drain Street Surface Flow Pattern



# Existing Drain System Inlets



ARLINGTON STREET (FACING WEST FROM RIVER AVENUE)




CATCH BASINS ON ARLINGTON STREET BETWEEN RIVER AVENUE AND HESPERIAN AVENUE AT THE LOW POINT

# Gate Entrance to SCE Property



RIVER AVENUE SOUTH OF ARLINGTON STREET (FACING SOUTH)



DOOR AT END OF RIVER AVENUE

# Typical Backyard Wall against SCE Property



HOLE ALONG BLOCK WALL BETWEEN THE NURSERY AND PRIVATE PROPERTIES

Drainage Swale and Inlet on SCE Property




V-DITCH ON NURSERY SITE BEHIND BLOCK WALL



GRATED CATCH BASIN ALONG V-DITCH

### Interim Drainage Improvements








Legend

Switting Flow Directors
Storm Down

CONTRACTOR OF STREET

Catch Busin

### Proposed Storm Drain Improvements






River Avenue Storm Drain




Legend


Surface Plaw Circuition Storm Drain O Calch Basin


















### 42

# Arlington Avenue Flooding

February 7, 2009