

EXHIBIT B - EXISTING CONDITIONS

Page 1 of 2



Front of Property (East Elevation)



Existing curb cut and driveway



Existing double-hung wood windows



Red "S" shaped clay tile

EXHIBIT B - EXISTING CONDITIONS
Page 2 of 2



Tripartite wood window



Side of dwelling (North Elevation)



Location of proposed rear addition



Location of new detached accessory structure