

EXISTING CONDITIONS

Page 1 of 2



Front of Property (South Elevation)



Existing stucco cladding



Existing casement windows



Existing aluminum and stucco trim

EXISTING CONDITIONS

Page 2 of 2



Existing two-car garage to be demolished



Existing neighboring detached garage (west)



Rear of the primary dwelling



Existing two-story structure adjacent to property (west)