

Front Elevation



Porch



Street view - looking south



West elevation





Contributing structure at rear



Vernacular Italianate – Rear structure





Front Elevation - Single story craftsman





**Side elevation – Structure adjacent to neighbor’s driveway**





Drive approach and ribbon drive way



Side elevation – facing front





Windows along side elevation





Original short window



**Front Porch - foundation failing**





**Porch column- stucco over brick facade**



**Roof rafters failing**







**Roof and eave deteriorated**



**Original feature window – side elevation**



Non-contributing apartments across street





Remanding photos are of two-story building within district



