1060 Maine Avenue, Long Beach, CA 90813

562-432-8999

1044 Maine Avenue in the Willmore City <u>Historic District</u>
Asterisks indicate violations of law, code, ordinance or whatever
Building Code

- \*\* Building sat abandoned for 3 1/2 years. Some windows not boarded, broken by vandals with rocks. Vandals got inside.
- ₩ When work finally began, contractor didn't put up an electric pole
- ★Used a gasoline-powered generator, audible a block away
  (With no electric for lighting and no night watchperson, vandals got in overnight and stole newly installed copper plumbing and wiring.)
- ★ Stopped work for a matter of months. Left a dumpster at the curb for 1-2 months, taking up needed parking and accruing charges
  - <u>Certificate of Appropriateness</u>—required for architectural work in a historic district
  - Specified stucco, light beige/tan (This color was visible at time of purchase, surely original to building)
  - Repair or replace windows with same type, wood sill and frame to remain
- >Proposed wooden band between 1st and 2nd floors should have been crossed out, not original to building (Band trim appears on buildings of the period, but are much narrower and are stucco.)
- \*Wood band at rooftop not original, should have been crossed out

  Violations of Certificate of Appropriateness
- ★ Stucco is grey, not original beige
- \*Windows are grossly inauthentic, wood sill and frame removed
- \* Added inauthentic awnings, not on C of A

  Even the concrete is not authentic
- \* Rendered my fence illegal

## Before



A car was parked at the curb, so it was taken at an angle. The grey paint had been blasted off, so it was the original beige/tan stucco at purchase.

No "after" picture available, so this will have to do.

KEYNOTES

NEW STUCCO

PATCH AND REPAINT EXISTING TRIM

NEW STUCCO BANDING / ACCENT TRIM

REPAIR OR REPLACE WOOD WINDOWS NEW LIGHT FIXTURE

NEW IRON GATE (6'6" MGK)

NEW FRENCH DOOR TO MATCH EXISTING

NEW ADDRESS NUMBER - Black | Bronze

NEW STREET TREE

West Elevation

1044 MAINE FACADE IMPROVEMENT CITY OF LONG BEACH

Elevation

stud**i©©©**leven



City of Long Beach Department of Development Services Historic Preservation Division 333 West Ocean Blvd., 5<sup>th</sup> floor Long Beach, CA 90802 (562) 570-6194 Fax: (562) 570-6068

## CERTIFICATE OF APPROPRIATENESS

Minor (Staff) Project Application

Please print legibly or type	03/25/2010		FY 10-			HP10-	00#89
PROJECT ADDRESS (NOT MAILING LIST): 1044 Maine Ave.			HISTORIC DISTRICT/LANDMARK NAME: Willmore/ Drake Park				
PPLICANT'S NAME: City of Long Beach Neighborhood Services Bureau	en di		PROPERTY OWNER'S NA City of Long Beach Neighbo	11-11-1	Bureau		
PPLICANT'S ADDRESS: 144 W. Ocean Blvd. STE 1700	. 434 : Kilan (1		PROPERTY OWNER'S AD 444 W. Ocean Blvd. STE 17				
TY, STATE, ZIP: ong Beach, CA. 90802			CITY, STATE, ZIP: Long Beach, CA 90802				
ELEPHONE (INCLUDING AREA CODE): 562-570-5585			TELEPHONE (INCLUDING 562-570-5585	AREA CODE):			
MAIL ADDRESS: gilberto.contreras@longbeach.gov			EMAIL ADDRESS: gilberto.confreras@longbea	ich.gov			
RIMARY CONTACT PERSON:		1977 18. juli	☐ Proper	ty Owner			
Only check a box if it a In addition, please briefly do	escribe your project	t noting n		ation, and			sed.
☐ New Construction ☑ Restoration/Rehabilitation	☐ Reloca ☐ Alterat		☐ Addition☐ Demolition		Signage Other:	e/Awning	
Remodel an existing two-story m finish stucco in a light tan/beige of to remain, install two wood French	color, repair and/or re th doors on front (we	eplace wo est) elevat	od sash windows willion of second floor,	th the same maintain the	type wind fixed win	dows, woo dows with	od trim and four mullio
finish stucco in a light tan/beige of to remain, install two wood French on the front (west) elevation of the maintain the exiting balcony deep arapet of the building, and the linstall a wrought iron fence at the front elevation with wood slats baccent color.	color, repair and/or re th doors on front (we e first floor, install a ck facia, the propos band below the wind e front entry to mato beneath and projecti	eplace wo est) elevat wrought i ed stucco dow sills s th the bald ing rafter	ood sash windows willon of second floor, front balcony rail be band between the shall be constructed cony railing design, a tails in its current c	ith the same maintain the lling 36" high first and so of wood and and maintair ondition. Th	type wind fixed win h incorpora econd floo d no more h the proje e eave m	dows, woo dows with ating the c or, the bar than 2.5' ecting woo ay be pai	od trim and four mulli- original rail and at the inches de
finish stucco in a light tan/beige of to remain, install two wood Frencon the front (west) elevation of the maintain the exiting balcony deparapet of the building, and the linstall a wrought iron fence at the front elevation with wood slats baccent color.	color, repair and/or re th doors on front (we e first floor, install a ck facia, the propos band below the wind e front entry to mato beneath and projecti	eplace wo est) elevat wrought i ed stucco dow sills s th the bald ing rafter	ood sash windows willon of second floor, front balcony rail be band between the shall be constructed cony railing design, a tails in its current c	ith the same maintain the lling 36" high first and so of wood and and maintair ondition. Th	type wind fixed win h incorpora econd floo d no more h the proje e eave m	dows, woo dows with ating the c or, the bar than 2.5' ecting woo ay be pai	od trim and four mulli- original rail and at the inches de
finish stucco in a light tan/beige of to remain, install two wood Frencon the front (west) elevation of the maintain the exiting balcony deparapet of the building, and the linstall a wrought iron fence at the front elevation with wood slats baccent color.	color, repair and/or re th doors on front (we e first floor, install a ck facia, the propos band below the wind e front entry to mato beneath and projecti	eplace wo est) elevat wrought i ed stucco dow sills s th the bald ing rafter	ood sash windows willon of second floor, ron front balcony rail band between the shall be constructed cony railing design, a tails in its current c	ith the same maintain the lling 36" high first and so of wood and and maintair ondition. Th	type wind fixed win h incorpora econd floo d no more h the proje e eave m	dows, woo dows with ating the c or, the bar than 2.5' ecting woo ay be pai	od trim and four mulli- original rail and at the inches de
finish stucco in a light tan/beige of to remain, install two wood Frence on the front (west) elevation of the maintain the exiting balcony deparapet of the building, and the install a wrought iron fence at the front elevation with wood slats accent color.  REASON FOR CHANGE(S)	color, repair and/or re th doors on front (we e first floor, install a ck facia, the propos band below the wind e front entry to mato beneath and projecti	eplace wo est) elevat wrought i ed stucco dow sills s th the bald ing rafter	od sash windows willon of second floor, ron front balcony rate band between the shall be constructed only railing design, a tails in its current of property for participat	ith the same maintain the ling 36" high first and so of wood and maintair ondition. The lion in the Ne	type wind fixed win incorpora econd floo d no more the proje e eave m	dows, woo dows with ating the c or, the ba than 2.5' cting woo ay be pai	od trim and four mullipriginal raill and at the raill inches de deave on inted a dar
finish stucco in a light tan/beige of to remain, install two wood Frenci on the front (west) elevation of the maintain the exiting balcony deciparapet of the building, and the linstall a wrought iron fence at the front elevation with wood slats by	color, repair and/or re th doors on front (we e first floor, install a ck facia, the propos band below the wind e front entry to mato beneath and projecti	eplace wo est) elevat wrought i ed stucco dow sills s th the bald ing rafter	ood sash windows willon of second floor, ron front balcony rail band between the shall be constructed cony railing design, a tails in its current c	ith the same maintain the ling 36" high first and so of wood and maintair ondition. The lion in the Ne	type wind fixed win incorpora econd floo d no more the proje e eave m	dows, woo dows with ating the c or, the ba than 2.5' cting woo ay be pai	od trim and four mullipriginal raill and at the raill inches de deave on inted a dar
finish stucco in a light tan/beige of to remain; install two wood French on the front (west) elevation of the maintain the exiting balcony deparapet of the building, and the install a wrought iron fence at the front elevation with wood slats is accent color.  B. REASON FOR CHANGE(S)  TOTAL SQUARE FEET OF THIS PROJECT:  SOMM RES GAR  If, the undersigned, declare under penalty application is true and correct. In additional until a Certificate of Appropriateness neither this application nor a subsequer	colof, repair and/or resh doors on front (we he first floor, install a ck facia, the proposed on below the winder front entry to match beneath and projection. Substantial rehaming of perjury under the law fon, I understand that I chairly issued by the Culturally issued Certificate of	eplace wo est) elevat wrought i ed stucce dow sills s th the bald ing rafter abilitation of ws of the St cannot proc al Heritage f Appropriate	valuation of work of property for participat talls in its current of property for participat valuation of work of \$750,000.	th the same maintain the maintain the ling 36" high first and so of wood an and maintain ondition. The lion in the Ne process of the linformation	type wind type wind fixed win incorporate cond flood no more at the project eave many this certification of this Certification of the necessary in the necessar	dows, woo dows with ating the cor, the bar than 2.5 cting woo ay be paid Stabilization:  Stabilization:  Constitute of Applicate of Applicate of Applicate of Applicate of Applications of the core of	od trim and four mulli original rail or at the inches de deave on inted a dail on Program
finish stucco in a light tan/beige of to remain, install two wood French on the front (west) elevation of the maintain the exiting balcony deparapet of the building, and the linstall a wrought iron fence at the front elevation with wood slats accent color.  REASON FOR CHANGE(S)  OTAL SQUARE FEET OF THIS PROJECT: OMM RES GAR  the undersigned, declare under penalty application is true and correct. In additional until a Certificate of Appropriateness neither this application nor a subsequer	color, repair and/or resh doors on front (we he first floor, install a ck facia, the proposed pand below the winder front entry to match beneath and projection.  Substantial rehabition, I understand that I con, I understand that I understand that I con, I understand that I	eplace wo est) elevat wrought i ed stucco dow sills s th the bald ing rafter abilitation of ws of the St cannot proc al Heritage f Appropriate under the C	valuation of work of property for participat tails in its current of property for participat valuation of California that the end with the environment of Long Beach Municipat Commission or the Histories supersedes the ness supersedes the nest conductive of Long Beach Municipation of Section 1988 (1998).	ith the same maintain the maintain the ling 36" high first and so of wood and maintain ondition. The lion in the Ne part of the lion in the lion in the lion in the lion in the Ne part of the lion in th	type wind type wind fixed win incorpora econd floo d no more the proje e eave m ighborhood  IS APPLICATI  on this Certifi equested in ion Officer.	dows, woo dows with ating the cor, the bar than 2.5 cting woo ay be paid Stabilization:  Stabilization:  Constitute of Applicate of Applicate of Applicate of Applicate of Applications of the core of	od trim and four mulli original rail or at the inches de deave on inted a dail on Program
finish stucco in a light tan/beige of to remain, install two wood French on the front (west) elevation of the maintain the exiting balcony decay parapet of the building, and the linstall a wrought iron fence at the front elevation with wood slats be accent color.  REASON FOR CHANGE(S)  The undersigned, declare under penalty application is true and correct. In additional until a Certificate of Appropriateness neither this application nor a subsequence in the contract of the	colof, repair and/or resh doors on front (we he first floor, install a ck facia, the proposed pand below the wind front entry to match beneath and projection. Substantial rehams on, I understand that I do is issued by the Culturally issued Certificate of their applicable permits of the perm	eplace wo est) elevat wrought i ed stucco dow sills s th the bald ing rafter abilitation of ws of the St cannot proc al Heritage f Appropriate under the C	valuation of work of \$750,000.  Valuation of the Histories supersedes the next of Long Beach Municipal Commission of the Histories supersedes the next of Long Beach Municipal Commission of the Histories supersedes the next of Long Beach Municipal Commission of the Histories supersedes the next of Long Beach Municipal Commission of the Histories supersedes the next of Long Beach Municipal Commission of the Histories supersedes the next of Long Beach Municipal Commission of the Light of Long Beach Municipal Commission of the Histories supersedes the next of Long Beach Municipal Commission of the Histories supersedes the next of Long Beach Municipal Commission of the Histories supersedes the next of Long Beach Municipal Commission of the Histories supersedes the next of Long Beach Municipal Commission of the Histories supersedes the next of Long Beach Municipal Commission of the Histories supersedes the next of Long Beach Municipal Commission of the Histories supersedes the next of Long Beach Municipal Commission of the Histories supersedes the next of Long Beach Municipal Commission of the Histories supersedes the next of Long Beach Municipal Commission of the Histories supersedes the next of Long Beach Municipal Commission of the Histories supersedes the next of Long Beach Municipal Commission of the Histories supersedes the next of Long Beach Municipal Commission of the Histories supersedes the next of Long Beach Municipal Commission of the Histories supersedes the next of Long Beach Municipal Commission of the Histories supersedes the next of Long Beach Municipal Commission of the Histories supersedes the next of Long Beach Municipal Commission of the Histories supersedes the next of Long Beach Municipal Commission of the Histories supersedes the next of Long Beach Municipal Commission of the Histories supersedes the next of Long Beach Municipal Commission of the Histories supersedes the next of Long Beach Municipal	th the same maintain the maintain the ling 36" high first and so of wood and maintain ondition. The lion in the Ne prince of the line of t	type wind type wind fixed win incorporate ond flood no more the project eave mighborhood is application this Certification Officer, the necessary.  03/26	dows, woo dows with atting the cur, the bar than 2.5' cting woo ay be paid Stabilization:	od trim and four mulli priginal rail at the inches de deave on inted a da on Program propriatenes ation unless derstand the permits and
finish stucco in a light tan/beige of to remain; install two wood French on the front (west) elevation of the maintain the exiting balcony deep parapet of the building, and the linstall a wrought iron fence at the front elevation with wood slats accent color.  3. REASON FOR CHANGE(S)  OTAL SQUARE FEET OF THIS PROJECT: COMM RES GAR  4. the undersigned, declare under penalty application is true and correct. In additional until a Certificate of Appropriateness neither this application nor a subsequence of Gilberto Contreras  CEQA Review:	colof, repair and/or resh doors on front (we e first floor, install a ck facia, the proposed pand below the winder front entry to match beneath and projection. Substantial rehamants is issued by the Culturally issued Certificate of their applicable permits of the proposed permits of the propos	eplace wo est) elevat wrought i ed stucce dow sills s h the bald ing rafter abilitation of Appropriate under the C	valuation of work of \$750,000.  Valuation of the Histories supersedes the next of Long Beach Municipal Commission of the Histories supersedes the next of Long Beach Municipal Commission of the Histories supersedes the next of Long Beach Municipal Commission of the Histories supersedes the next of Long Beach Municipal Commission of the Histories supersedes the next of Long Beach Municipal Commission of the Histories supersedes the next of Long Beach Municipal Commission of the Light of Long Beach Municipal Commission of the Histories supersedes the next of Long Beach Municipal Commission of the Histories supersedes the next of Long Beach Municipal Commission of the Histories supersedes the next of Long Beach Municipal Commission of the Histories supersedes the next of Long Beach Municipal Commission of the Histories supersedes the next of Long Beach Municipal Commission of the Histories supersedes the next of Long Beach Municipal Commission of the Histories supersedes the next of Long Beach Municipal Commission of the Histories supersedes the next of Long Beach Municipal Commission of the Histories supersedes the next of Long Beach Municipal Commission of the Histories supersedes the next of Long Beach Municipal Commission of the Histories supersedes the next of Long Beach Municipal Commission of the Histories supersedes the next of Long Beach Municipal Commission of the Histories supersedes the next of Long Beach Municipal Commission of the Histories supersedes the next of Long Beach Municipal Commission of the Histories supersedes the next of Long Beach Municipal Commission of the Histories supersedes the next of Long Beach Municipal Commission of the Histories supersedes the next of Long Beach Municipal Commission of the Histories supersedes the next of Long Beach Municipal Commission of the Histories supersedes the next of Long Beach Municipal Commission of the Histories supersedes the next of Long Beach Municipal	th the same maintain the maintain the ling 36" high first and so of wood and maintain ondition. The lion in the New Medical Changes in oric Preservatived to obtain cipal Code.  Date NE	type wind type wind fixed win incorporate cond flood no more the project example and the project examp	dows, woo dows with ating the cor, the bar than 2.5 cting woo ay be paid Stabilization:  Stabilization:  Constitute of Applicate of Applicate of Applicate of Applicate of Applications of the core of	od trim and four mulli original rail or at the inches de deave on inted a dail on Program
finish stucco in a light tan/beige of to remain; install two wood French on the front (west) elevation of the maintain the exiting balcony deep parapet of the building, and the linstall a wrought iron fence at the front elevation with wood slats be accent color.  3. REASON FOR CHANGE(S)  OTAL SQUARE FEET OF THIS PROJECT: COMM RES GAR  4. the undersigned, declare under penalty application is true and correct. In additional until a Certificate of Appropriateness neither this application nor a subsequence of the penalty of the contract of	MISC  of perjury under the law is issued by the Culturatity issued Certificate of ther applicable permits of ther applicable permits of the proyed  FOR DEPARTMEN  ENDOR TO THE PROYED T	eplace wo est) elevat wrought is ed stucced ow sills such the balcing rafter abilitation of the Stannot procal Heritage of Appropriate under the Communication of the Stannot procal Heritage of Appropriate under the Communication of the Stannot procal Heritage of Appropriate under the Communication of the Stannot procal Heritage of Appropriate under the Communication of the Stannot procal Heritage of Appropriate under the Communication of the Stannot procal Heritage of the Stannot procal Heri	valuation of work of \$750,000.  Valuation of the Histories supersedes the next of Long Beach Municipal Commission of the Histories supersedes the next of Long Beach Municipal Commission of the Histories supersedes the next of Long Beach Municipal Commission of the Histories supersedes the next of Long Beach Municipal Commission of the Histories supersedes the next of Long Beach Municipal Commission of the Histories supersedes the next of Long Beach Municipal Commission of the Light of Long Beach Municipal Commission of the Histories supersedes the next of Long Beach Municipal Commission of the Histories supersedes the next of Long Beach Municipal Commission of the Histories supersedes the next of Long Beach Municipal Commission of the Histories supersedes the next of Long Beach Municipal Commission of the Histories supersedes the next of Long Beach Municipal Commission of the Histories supersedes the next of Long Beach Municipal Commission of the Histories supersedes the next of Long Beach Municipal Commission of the Histories supersedes the next of Long Beach Municipal Commission of the Histories supersedes the next of Long Beach Municipal Commission of the Histories supersedes the next of Long Beach Municipal Commission of the Histories supersedes the next of Long Beach Municipal Commission of the Histories supersedes the next of Long Beach Municipal Commission of the Histories supersedes the next of Long Beach Municipal Commission of the Histories supersedes the next of Long Beach Municipal Commission of the Histories supersedes the next of Long Beach Municipal Commission of the Histories supersedes the next of Long Beach Municipal Commission of the Histories supersedes the next of Long Beach Municipal Commission of the Histories supersedes the next of Long Beach Municipal Commission of the Histories supersedes the next of Long Beach Municipal Commission of the Histories supersedes the next of Long Beach Municipal	th the same maintain the ling 36" high first and so of wood and and maintain ondition. The lion in the Ne covered by The enformation of the line of th	type wind type wind type wind fixed win incorpora econd floo d no more the proje e eave m  ghborhood  is application of this Certification of the necessar  gree: 9.3% Sui	dows, woo dows with atting the cor, the bar than 2.5 octing woo ay be particate of Aprilia applications further unary building	od trim and four mulli- indiginal railland at the inches de deave on inted a dark on Program on Program on Program atton unless derstand that permits and

Notes on 1044 Maine in the Willmore City Historic District; three minutes isn't a long time

Windows are probably the most important element in historic preservation and it's hard to explain why, so I won't take up space in the attempt.

Please get out of your car to look closely at the downstairs triple windows. Look at the triple window at the house to the north, which is historically correct. It is all one unit, with no stucco in between, as with the windows at 1044. As 1044 is stucco, it should not have frames around the windows. In stucco construction, the window frames are flush with the stucco. See the attached before picture.

The original windows were repairable and could have been restored for much less money than the new ones cost. But, hey, it was only tax money!

There are two outfits in long Beach that repair and/or restore old windows for much less money than the replacements cost. Tax money only appears to be free.

The originals were old-growth lumber, which is virtually termite-proof. The new ones, recent-growth lumber, are a termite bug-fet.

The whole job probably cost two or three times what it should have. Architects, who should have known better, were even brought in. Their services would not have been needed if the job were being done right. I believe they designed the windows, and submitted a bill, which cost more tax money.

The building has been sold. Did it recoup the tax money spent unnecessarily? I doubt it. Landlords buy property based on condition and the bottom line. Architecture seems to play a minor part in pricing. Oh well, it was only tax money.

Iong Beach needs jobs, right? The contractor appears to be from the San Fernando Valley.

And by the way, the application for the Certificate of Appropriateness no longer asks for a photo of the building as it stands. It should be a requirement. Then the staffer who approved this one would have realized the wood bands weren't original.