



Source: Historical Resources Report prepared by Galvin Preservation Associates, February 2013.



Figure 15: Front elevation of 2810 E. 1<sup>st</sup> Street, view to the southeast, February 21, 2013. Source: GPA.



Figure 16: Front porch details, 2810 E. 1<sup>st</sup> Street, view to the southeast, February 21, 2013. Source: GPA.



Figure 17: Window details at east side elevation, 2810 E. 1<sup>st</sup> Street, view to the southwest, February 21, 2013. Source: GPA.



Figure 18: Rear elevation of 2810 E. 1<sup>st</sup> Street, view to the north, March 9, 2011. Image courtesy of LSA Associates.



Figure 9: Rear elevation of 2810 E. 1<sup>st</sup> Street. Picture taken March 9, 2011.



Figure 10: Side/rear elevations of 2810 E. 1<sup>st</sup> Street garage. Picture taken March 9, 2011.



PHOTOGRAPH 26: Photo taken 3/9/2011



PHOTOGRAPH 27: Photo taken 3/9/2011

LSA

ATTACHMENT A-14

2810 E 1st Street  
Historic Structure Report  
Site Photographs