
# ADA and drainage deficiencies in a two block area:

25th Street at Santa Fe Avenue 2500 Block of Cota and Seabright Avenues at Willow Street



#### Inadequate ADA Access



Seabright Avenue at Willow Street

Inadequate ADA Access


Only one corner has wheelchair access

Seabright Avenue at Willow Street


Inadequate ADA Access

Street conditions are perilous for wheelchairs, walkers and canes

Seabright Avenue at Willow Street






















25th Street at Cota Avenue

A great place to start infrastructure improvements

25th Street at Cota Avenue



Thank you.

25<sup>th</sup> Street at Cota Avenue