

# **Certificate of Appropriateness**


224 E. Broadway

American Hotel

Designated Historic Landmark Building



### **American Hotel**




Façade details revealed after selective demolition






# **Study Session – October 2010**



historic photograph revealing original architectural detail



**Façade Revisions** 





# **Secondary Elevations**



#### East Elevation

- Repair and replace deteriorated brick/mortar
- Clean surface using gentlest method possible



West Elevation

- Remove vent system
- Remove fire escape ladders
- Maintain fire escape balconies
- Replace existing windows
- Paint and patch as needed





# **Secondary Elevations**



#### South Elevation


- Replace existing windows
- New exterior stairs to be installed for egress
- Modern screening wall added







**Examples** 



Kress Lofts



Walker Building



# **Conditions of Approval**

- Material samples
- Brick repointing
- Elements removed
- Sidewalk
- Signage, mechanical equipment
- Lot line adjustment
- Proper moth-balling of building, if necessary