

City of Long Beach ---Arborist Report

10/3/2015

Belmont Shore - 2nd St {Quincy, {South Side}}

Address locations will be identified and placed in order from Quincy ave to Bayshore Ave

Address	# Of	Common Name	Condition	Soil Cond.	S/W Offsets	Tree Skirt	Tree Grate	Lock on Grate
4600 E 2nd Street	1	Ornamental Pear	Good	OK	None	Bent Top	Good	No
4606 E 2nd Street (W / Tree)	1	Ornamental Pear	Good	OK	None	OK	Good	No
4606 E 2nd Street (S / Tree)	1	Ornamental Pear	Good	OK	None	Missing Bolts	Good	No
4610 E 2nd Street	1	Ornamental Pear	Good	OK	None	Bolts & Bent	Good	Yes
4702 E 2nd Street (Roycroft Side)	2	Queen Palm	Good	OK	None	No Skirt	No Grate	No
4706 E 2nd Street	1	Ornamental Pear	Fair	Dry	None	OK	Good	No
4716 E 2nd Street	1	Evergreen Pear	Good	Dry	None	OK	Good	No
4720 E 2nd Street	1	Ornamental Pear	Fair to Good	Dry	None	Loose	Good	No
4726 E 2nd Street (Park Ave Side)	1	Ornamental Pear	Good	OK	None	OK	Good	No
4800 E 2nd Street (Park Ave Side)	1	Ornamental Pear	Good	OK	None	OK	Good	No
184 Park Ave	1	Queen Palm	Good	OK	None	OK	Good	No
4814 E 2nd Street	1	Ornamental Pear	Good	OK	None	OK	Good	No
4820 E 2nd Street	1	Ornamental Pear	Good	OK	None	OK	Good	No
4910 E 2nd Street	2	Ornamental Pear	Good	OK	None	OK	Good	No
4924 E 2nd Street	1	Ornamental Pear	Dead / Rem	Dry	None	Loose	Good	Yes
5004 E 2nd Street	1	Ornamental Pear	Good	Dry	None	Loose	Good	Yes
5016 E 2nd Street	1	Ornamental Pear	Good	Dry	None	Loose	Good	No
5020 E 2nd Street	1	Ornamental Pear	Good	OK	None	Loose	Good	Yes
5100 E 2nd Street (Granada St Side)	1	King Palm	Good	OK	None	No Skirt	No Grate	No
5100 E 2nd Street (Granada St Side)	1	Queen Palm	Good	OK	None	No Skirt	No Grate	No
5100 E 2nd Street	1	Ornamental Pear	Good	OK	None	Loose	Good	No
5114 E 2nd Street	1	Ornamental Pear	Good	OK	None	OK	Good	No
5128 E 2nd Street	1	Ornamental Pear	Good	OK	None	Loose	Good	Yes
5200 E 2nd Street / East Tree	1	Ornamental Pear	Good	OK	None	Loose	Good	No
5200 E 2nd Street / West Tree	1	Ornamental Pear	Good	OK	None	OK	Good	No
5232 E 2nd Street	1	Ornamental Pear	Good	OK	None	OK	Good	No
5236 E 2nd Street	1	Ornamental Pear	Good	OK	None	OK	Good	No
5242 E 2nd Street	1	Ornamental Pear	Dry	OK	None	Loose	Good	No
5252 E 2nd Street	1	Ornamental Pear	Good	Dry	None	Bolts & Loose	Good	No
5258 E 2nd Street	1	Ornamental Pear	Poor / Decline / Rem	OK	None	Loose	Good	No
5276 E 2nd Street	1	Ornamental Pear	Good	OK	None	Loose	Good	No
5282 E 2nd Street	1	Ornamental Pear	Good	OK	None	OK	Good	No
5296 E 2nd Street	1	Ornamental Pear	Good	OK	None	Loose	Good	No
5296 E 2nd Street (Glendora Side)	2	Ornamental Pear	Good	OK	None	OK	Good	No

185	Glendora Ave	1	Brisbane Box	Good	OK	None	No Skirt	No Grate	No
5300	E 2nd Street (Glendora Side)	1	Brisbane Box	Good	OK	None	No Skirt	No Grate	No
5300	E 2nd Street (Glendora Side)	Tree # 1	Ornamental Pear	Good	OK	None	OK	Good	No
5300	E 2nd Street (Glendora Side)	Tree # 2	Ornamental Pear	Good	OK	None	OK	Good	No
5300	E 2nd Street (Glendora Side)	Tree # 3	Ornamental Pear	Good	OK	None	OK	Good	No
5300	E 2nd Street (Glendora Side)	Tree # 4	Ornamental Pear	Dead / Rem	OK	None	OK	Good	No
5316	E 2nd Street	1	Ornamental Pear	Good	OK	None	OK	Good	No
5332	E 2nd Street	1	Ornamental Pear	Good	OK	None	OK	Good	No
5338	E 2nd Street	1	Ornamental Pear	Good	OK	None	OK	Good	No
5346	E 2nd Street	1	Ornamental Pear	Good	OK	None	Bent / Losse	1" Offset	No
5368	E 2nd Street	1	Stump / Heart Rot	N/A	OK	None	OK	Good	Yes
5374	E 2nd Street	1	Ornamental Pear	Good	OK	None	Loose	Good	No
Total		49							

Belmont Shore - 2nd St {Quincy} {North Side}

Address	# Of	Common Name	Condition	Soil Cond	S/W Offsets	Tree Skirt	Tree Grate	Lock on Grate
4601 E 2nd Stret	2	Ornamental Pear	Good	OK	None	OK	Good	
4609 E 2nd Street	3	Ornamental Pear	Good	OK	None	OK	Good	No
4707 E 2nd Street	1	Ornamental Pear	Good	OK	None	OK	Good	No
4713 E 2nd Street	1	Ornamental Pear	Good	OK	None	OK	Good	No
4725 E 2nd Street (Park Ave Side)	Tree # 1	Ornamental Pear	Good	OK	None	OK	Good	No
4725 E 2nd Street (Park Ave Side)	Tree # 2	Ornamental Pear	Good	OK	None	OK	Good	No
4725 E 2nd Street (Park Ave Side)	Tree # 3	Ornamental Pear	Good	OK	None	OK	1" Offset	No
4725 E 2nd Street (East / Tree)	1	Ornamental Pear	Good	OK	None	OK	1" Offset	No
4725 E 2nd Street (West / Tree)	1	Ornamental Pear	Fair to Good	OK	None	Loose	Good	No
204 Park Ave	3	Mexican Fan Palm	Good	OK	None	No Skirt	No Grate	No
4801 E 2nd Street (Park Ave Side)	Tree # 1	Evergreen Pear	Good	OK	None	OK	Good	No
4801 E 2nd Street (Park Ave Side)	Tree # 2	Evergreen Pear	Good	OK	None	OK	1' Offset	No
4801 E 2nd Street (Park Ave Side)	Tree # 3	Evergreen Pear	Good	OK	None	OK	Good	No
4801 E 2nd Street	1	Ornamental Pear	Good	OK	None	OK	Good	No
4817 E 2nd Street	1	Ornamental Pear	Fair to Good	Dry	None	OK	Good	No
4821 E 2nd Street	1	Ornamental Pear	Dead / Rem	Dry	None	OK	Good	No
4905 E 2nd Street	1	Ornamental Pear	Good	OK	None	OK	Good	No
4913 E 2nd Street	1	Ornamental Pear	Good	OK	None	Loose	Good	No
4917 E 2nd Street	1	Ornamental Pear	Good	OK	None	OK	Good	No
4925 E 2nd Street	1	Ornamental Pear	Good	Dry	None	Loose	Good	No
5009 E 2nd Street	1	Ornamental Pear	Fair to Good	Dry	None	OK	Good	No
5015 E 2nd Street (Granada Side)	2	Ornamental Pear	Good	OK	None	OK	Good	No
5025 E 2nd Street	1	Ornamental Pear	Fair Cond.	Dry	None	OK	Good	No
5109 E 2nd Street (Granada Side)	1	Ornamental Pear	Good	OK	None	OK	Good	No
5109 E 2nd Street (East / Tree)	1	Ornamental Pear	Poor / Aphids / Rem	Dry	None	OK	Good	No

5109	E 2nd Street (West / Tree)	1	Ornamental Pear	Good	Dry	None	OK	Good	No
5209	E 2nd Street	1	Ornamental Pear	Good	OK	None	Loose	Good	No
5211	E 2nd Street	1	Ornamental Pear	Good	OK	None	OK	Good	No
5215	E 2nd Street	1	Ornamental Pear	Good	OK	None	Loose	Good	No
5229	E 2nd Street	1	Ornamental Pear	Fair to Good	Dry	None	OK	Good	No
5239	E 2nd Street	1	Ornamental Pear	Good	OK	None	Loose	Good	No
5243	E 2nd Street	1	Ornamental Pear	Fair	Dry	None	OK	Good	No
5257	E 2nd Street	1	Ornamental Pear	Poor / Rem	To Wet	None	OK	Good	No
5265	E 2nd Street	1	Ornamental Pear	Good	OK	None	Loose	Good	No
5269	E 2nd Street	1	Ornamental Pear	Good	OK	None	Loose	Good	No
5283	E 2nd Street	1	Ornamental Pear	Good	OK	None	Loose	Good	No
5287	E 2nd Street	1	Ornamental Pear	Good	OK	None	Loose	Good	No
203	Glendora Ave	1	Evergreen Pear	Good	OK	None	Loose	Good	No
203	Glendora Ave	1	Ornamental Pear	Good	OK	None	Loose	Good	No
5305	E 2nd Street (Glendora Side)	2	Ficus Tree	Good	OK	Pots	No Skirt	No Grate	No
5307	E 2nd Street	1	Ornamental Pear	Good	OK	None	Loose	Good	No
5313	E 2nd Street	1	Ornamental Pear	Good	OK	None	OK	Good	No
5331	E 2nd Street	1	Ornamental Pear	Poor / Rem	OK	None	Loose	Good	No
5349	E 2nd Street	1	Ornamental Pear	Good	OK	None	Loose	Good	No
5353	E 2nd Street (East / Tree)	1	Ornamental Pear	Good	OK	None	OK	Good	No
5353	E 2nd Street (West / Tree)	1	Ornamental Pear	Good	OK	None	Loose	Good	No
5375	E 2nd Street	1	Ornamental Pear	Good	OK	None	OK	1" Depress	Yes
Total		53							

Please note:

Looking at these trees, I found in most cases the pears are in fair to good condition, some of the trees are in stress which can be contributed to high heat, lack of water, and smog. The trees leaves are beginning to curl which is a sign that fall is approaching and they are about to loose their leaves. Overall I found most of the trees to be in fair to good condition, there are (7) trees that will need to be removed as well as (1) stump. Please note the tree that fell at 5368 E 2nd St fell due to heart rot in where decay set in which in turn weakened the trees structural stability causing the tree to fall.