

Big Belly Issues

Location	Issues
1. NE CORNER 2ND AND ROYCROFT	BATTERY REPLACEMENT
2. NW CORNER 2ND AND PARK	MISSING POSTER FRAME
3. PARK AVE NE SIDE NEAR PHILZ	MISSING POSTER FRAME, NEEDS NEW BUBBLE
4. NE CORNER 2ND AND PARK	NEEDS NEW BUBBLE
5. NORTHSIDE BETWEEN ARGONNE AND ST. JOSEPH NEAR AT&T	MISSING POSTER FRAME
6. NW CORNER 2ND AND GRANADA	MISSING POSTER FRAME
7. GRANADA NE SIDE	NEEDS NEW BUBBLE
8. NW CORNER 2ND AND CORONA	MISSING POSTER FRAME
9. NE CORNER 2ND AND CORONA	MISSING POSTER FRAME
10. NORTHSIDE BETWEEN COVINA AND CORONA AT BELMONT SPA	MISSING POSTER FRAME PIECE, ASH TUBE
11. NW CORNER 2ND AND COVINA	NEW BUBBLE, NEW BATTERY, SCREW FOR LOCK
12. NE CORNER 2ND AND COVINA	NEW BUBBLE
13. NORTHSIDE BETWEEN LAVERNE AND COVINA AT SAME DAY HEALTH	NEW BUBBLE; RAM ISSUE
14. NW CORNER 2ND AND LAVERNE	POSSIBLE DOOR SENSOR ISSUE
15. NORTHSIDE BETWEEN GLENDOURA AND LAVERNE AT DEAN ANTHONY	FRAME DAMAGE NEAR LOCKING REST, UNREPAIRABLE
16. NW CORNER 2ND AND GLENDOURA	MISSING POSTER FRAME
17. NE CORNER 2ND AND GLENDOURA	POSTER FRAME NEEDS TO BE REPAIRED
18. NORTHSIDE BETWEEN POMONA AND GLENDOURA AT CINNAHOLIC	POSTER FRAME NEEDS TO BE REPAIRED
19. NE CORNER 2ND AND SANTA ANA	MISSING POSTER FRAME; NO POWER NEED NEW BATTERY
20. NW CORNER 2ND AND CLAREMONT	NEEDS NEW BATTERY
21. SW CORNER 2ND AND BAYSHORE	ORIGINAL UNIT; REQUIRES NEW LOCK, SCREW FOR 2ND LOCK, MISSING POSTER FRAME
22. SE CORNER 2ND AND CLAREMONT	DAMAGE TO SIDE OF UNIT FRAME
23. SOUTHSIDE BETWEEN SANTA ANA AND CLAREMONT	NEED NEW LOCK ASSEMBLY, NEW BUBBLE

Big Belly Issues

Location	Issues
24 SW CORNER 2ND AND SANTA ANA	NEED NEW LOCK ASSEMBLY
25. SOUTHSIDE BETWEEN SANTA ANA AND POMONA AT RUNNERS HIGH	MISSING POSTER FRAME, NEEDS PAINT
26. SOUTHSIDE BETWEEN GLENDOURA AND POMONA AT THE BEACH	NEEDS NEW BATTERY
27. SE CORNER 2ND AND GLENDOURA	ELEVATED, NOT SECURED FROM GROUND
28. SW CORNER 2ND AND GLENDOURA	NEW BUBBLE, DOOR SENSOR ISSUE
29. SOUTHSIDE BETWEEN LAVERNE AND GLENDOURA AT TILLY'S	NEW BUBBLE, NEW BATTERY, PAINT TO BE REMOVED
30. SE CORNER AT 2ND AND LAVERNE	NEW BUBBLE, NEW BATTERY
31. SE CORNER AT 2ND AND COVINA	NOT SECURED FROM GROUND, NEEDS NEW LOCK
32. SW CORNER AT 2ND COVINA	NEW BATTERY, NEW BUBBLE
33. SOUTHSIDE BETWEEN CORONA AND COVINA AT VANS	NEW BUBBLE, KEY POSSIBLY BROKEN IN BUBBLE ACCESS LOCK
34. SE CORNER 2ND AND CORONA	DOOR SENSOR ISSUE
35. SW CORNER 2ND AND CORONA	PRESSURE WASHING REQUIRED IN FRONT OF UNIT
36. SOUTHSIDE BETWEEN NIETO AND CORONA BY CHASE	NEW BUBBLE, HANDLE FOR TRASH CHUTE, MISSING POSTER FRAME
37. SW CORNER 2ND AND NIETO	NEW BUBBLE
38. GRANADA SW SIDE	NOT ANCHORED TO GROUND
39. SOUTHSIDE BETWEEN ARGONNE AND GRANADA BY O MY SOLE	NEEDS NEW BATTERY, NEW BUBBLE, MISSING POSTER FRAME
40. SE CORNER 2ND AND ARGONNE	MISSING POSTER FRAME
41. SW CORNER 2ND AND ARGONNE	NEW BUBBLE
42. SOUTHSIDE BETWEEN ST JOSEPH AND ARGONNE NEAR SHORE STRENGTH LAB	NEW BATTERY, NEW BUBBLES
43. SW CORNER 2ND AND ST. JOSEPH	NOT ANCHORED TO GROUND, POSTER FRAME NEEDS RIVETS, NEW BATTERY
44. SE CORNER 2ND AND PARK	POSTER FRAMES MISSING
45. SW CORNER 2ND AND PARK	POSTER FRAME MISSING
46. SE CORNER 2ND AND ROYCROFT	POSTER FRAME PIECE MISSING, NEW BATTERY, NEW BUBBLE
47. SW CORNER 2ND AND ROYCROFT	NEW BATTERY, NEW BUBBLE
48. SOUTHSIDE BETWEEN QUINCY AND ROYCROFT BY SHELDRAKE	NEW LOCK, POSTER FRAME MISSING
49. SE CORNER 2ND AND QUINCY	NEW BATTERY