

REHABILITATION/RESTORATION/MAINTENANCE PLAN

Use this template to create a detailed work plan to be completed in the first 10 years of the contract. Recall that all work must be consistent with the Secretary of the Interior's Standards for Rehabilitation (see Application Guide Appendices), and properties which have already been fully rehabilitated or restored, and do not need additional work, are not eligible. Work that is visible from the public right-of-way, corrects any critical systems or structural deficiencies, and preserves historic features of the property should be given first priority. Duplicate this form as needed or provide additional sheets to include all work plan items. Remember that all exterior work on historic properties requires prior City approval through a Certificate of Appropriateness, and that any unpermitted work could be subject to fines, penalties, or might have to be modified, removed or redone at owner expense.

Property Name and Address: 781 Walnut Avenue, Long Beach, CA 90813

Item No.: House exterior & Trim Building Feature:	Detailed description of work: a) Restore cracked & broken siding b) Clean and repair molding trim c) Extensive surface prep to remove/scrape peeling paint d) Paint the house, trim & columns in colors that are in keeping with the craftsman palette.
Completion Year: 20 24	See Appendix 1
Plan to Use Long Beach Vendors For Materials/Labor: ☑ Yes (If Yes, specify/list) □ No	Specify/list: Negrini Painting, 1404 Ximeno Ave., Long Beach, CA 90804 (562) 986-9771
Item No.: 2 Front Facade Building Feature:	Detailed description of work: a) Rehabilitate the separating and sagging porch lintel b) Restore and rebalance the cracked & tilted porch & steps with new cement c) Restore base of columns which are deteriorating from moisture
Completion Year: 20 25	See Appendix 2
Plan to Use Long Beach Vendors For Materials/Labor: ☑ Yes (If Yes, specify/list) □ No	Specify/list:OnTapTrade Inc. Long Beach Business License: BU22220375 (541) 279-5486

Page 1 of 4 Revised 12/12/22

Item No.: 3 Building Feature: Window Rehabilitation	Detailed description of work: a) Restore broken glass in front picture window & 1 side window b) Restore wood frame screens c) Repair 10 double-hung wood-frame windows to restore operability (sash cords; weights; pulley mechanisms as needed) d) Remove inappropriate kitchen herb window & side aluminum window and replace with craftsman-style appropriate See Appendix 3
Completion Year: 20 26	
Plan to Use Long Beach Vendors For Materials/Labor: ✓ Yes (If Yes, specify/list) □ No	Specify/list: J.C. Window Restoration (562) 704-5979; Screen Pro 1 (562) 607-2558
Item No.:	Detailed description of work: a) Repair cracked foundation under NW corner, which is causing the
Building Feature: Foundation (Strengthening & Repair)	house to sag and permit water to get under the house b) Restore & repaint interior walls due to sagging foundation c) Restore & seal window frames which are separating due to sagging corner of the house.
Completion Year: 20 27	See Appendix 4
Plan to Use Long Beach Vendors For Materials/Labor: ☑ Yes (If Yes, specify/list) □ No	Specify/list: Golden Retrofit & Foundation Repair (800) 217-2458; Negrini painting (562) 986-9771; J.C. Window Restorati
Item No.: 5	Detailed description of work: a) Preserve foundation by installing gutters and French drains to pull
Building Feature: Drainage	water away from the house; prevent pooling and wetness under the house
Completion Year: 20 28	See Appendix 5
Plan to Use Long Beach Vendors For Materials/Labor: ☑ Yes (If Yes, specify/list) □ No	Specify/list: California Eco Design, 541 E. 8th St., Long Beach CA 90804 (C-27 License #1039801) (562) 279-6713

Page 2 of 4 Revised 12/12/22

Page 3 of 4 Revised 12/12/22

Property Name and Address: 781 Walnut Avenue, Long Beach, CA 90813

Item No.: 9 Roofing and Insulation Building Feature:	Detailed description of work: a) Repair broken support wood slats on underside of roof b) Plug holes to prevent light from shining through to the underside c) Repair torn & missing silver foil from underside of roof
	See Appendix 9
Completion Year: 20	
Plan to Use Long Beach Vendors For Materials/Labor:	Specify/list: TRC Roofing (562) 682-9027
Item No.: 10 Wood Frame/ Termite Mitigation Building Feature:	Detailed description of work: a) Preserve wood frame by removing the tree stump under the house that was left by the builder. Subterranean termites will continue to be an ongoing threat to the house's floors and frame. b) Stump needs to be removed either going through the top (remove & replace the floor) or using hand tools underneath the
Completion Year: 20	house. See Appendix 10
Plan to Use Long Beach Vendors For Materials/Labor:	Specify/list: Terminix in Long Beach (562) 230-6165; OnTapTrade Inc. Long Beach Business License: BU22220375 (541)

<u>NOTE</u>: Please ensure that the current condition of all building features proposed for rehabilitation/restoration/maintenance as part of this work plan are clearly photographed or otherwise documented and labelled as required, and submitted with the Mills Act Application (see Application Guide page 10).

To request this information in an alternative format or to request a reasonable accommodation, please contact the Development Services Department at longbeach.gov/lbds and 562.570.3807. A minimum of three business days is requested to ensure availability; attempts will be made to accommodate requests with shorter notice.

Page 4 of 4 Revised 12/12/22